

Fig. 1




Fig. 2A




Fig. 2B




Fig. 3




Fig. 4A




Fig. 4B

3/16




Fig. 5




Fig. 6

4/16

70




Fig. 7




Fig. 8




Fig. 9

6/16




Fig. 10




Fig. 11




Fig. 12




Fig. 13A




Fig. 13B

8/16




Fig. 14




Fig. 15




Fig. 16

9/16




Fig. 17




Fig. 18




Fig. 19

10/16




Fig. 20




Fig. 21




Fig. 22






Fig. 23




Fig. 24






Fig. 25






Fig. 26




Fig. 27



$B_{0,0}$	$B_{0,1}$	$B_{0,2}$	0	0	0	0	0	0	0	0
$B_{1,0}$	$B_{1,1}$	$B_{1,2}$	$B_{0,3}$	$B_{0,4}$	$B_{0,5}$	$B_{0,6}$	$B_{0,7}$	0	0	0
$B_{2,1}$	$B_{2,3}$	$B_{2,2}$	$B_{1,3}$	$B_{1,4}$	$B_{1,5}$	$B_{1,6}$	$B_{1,7}$	$B_{0,8}$	$B_{0,9}$	$B_{0,10}$

Fig. 28